



0+00,00

W = 0,00
N = 0,00
Pw = 0,00
Pn = 0,00
Wm = 0,00
Wk = 0,00




0+076,15

W = 0,66
N = 0,00
Pw = 0,00
Pn = 0,00
H = 0,00




0+168,15

W = 0,07
N = 0,06
Pw = 0,30
Pn = 0,48
H = 1,35




0+257,45

W = 0,05
N = 0,30
Pw = 0,00
Pn = 0,48
H = 1,40




0+340,10

W = 0,06
N = 0,07
Pw = 0,00
Pn = 0,39
H = 1,06




0+429,20

W = 0,06
N = 0,22
Pw = 0,00
Pn = 1,03
H = 1,35




0+527,15

W = 0,27
N = 0,57
Pw = 0,00
Pn = 0,39
H = 4,20




0+605,00

W = 0,87
N = 0,10
Pw = 3,20
Pn = 0,39
H = 3,73



0+695,50

W = 0,79
N = 0,10
Pw = 2,72
Pn = 0,00
H = 3,37




0+789,55

W = 0,82
N = 0,11
Pw = 3,11
Pn = 0,00
H = 3,65




0+042,90

W = 0,12
N = 0,20
Pw = 0,00
Pn = 1,00
H = 0,00




0+108,00

W = 0,06
N = 0,10
Pw = 0,00
Pn = 0,10
H = 1,17




0+193,10

W = 0,06
N = 0,21
Pw = 0,00
Pn = 0,38
H = 1,34




0+282,60

W = 0,02
N = 0,32
Pw = 0,00
Pn = 0,51
H = 1,43




0+364,70

W = 0,06
N = 0,21
Pw = 0,00
Pn = 0,23
H = 1,30




0+455,25

W = 0,06
N = 0,16
Pw = 0,00
Pn = 0,10
H = 1,23




0+557,45

W = 0,06
N = 0,95
Pw = 0,00
Pn = 1,82
H = 4,33




0+632,40

W = 0,10
N = 0,72
Pw = 2,37
Pn = 1,35
H = 4,55



0+732,40

W = 0,33
N = 0,24
Pw = 2,15
Pn = 0,37
H = 3,15



0+818,20

W = 0,62
N = 0,00
Pw = 2,91
Pn = 0,00
H = 3,52



0+059,15

W = 0,13
N = 0,70
Pw = 0,00
Pn = 2,62
H = 2,10

